

BEST AVAILABLE COPY

2/19




Figure 1E




Figure 1F

BEST AVAILABLE COPY

3/19

16

16




Figure 2A

Figure 2B




Fig. 2C

Fig. 2D

BEST AVAILABLE COPY

4/19

Fig 3A

16 →




Fig 3B

16 →





Fig 3C

16 →



BEST AVAILABLE COPY

5/19






Figure 4

BEST AVAILABLE COPY

6/19



BEST AVAILABLE COPY

7/19




Fig 5B

BEST AVAILABLE COPY

8/19




Figure 6

BEST AVAILABLE COPY

9/19




Fig. 7

BEST AVAILABLE COPY




Figure 8A




Figure 8B





Figure 9B






Figure 10C





FIG. 10D



Foot Stirrup
w/ Connecting Ring

Figure 11




FIG. 13A




FIG. 12




Figure 13B

19/19




Figure 14